



notice of violation

0037

NO. N 92-37-6-1

To the following Permittee or Operator:

Name Utah Fuel Co
Mine Skylark Mine ☐ Surface ☒ Underground ☐ Other
County Carbon State UT Telephone (801) 637-7925
Mailing Address P.O. Box 719, Helper UT 84526
State Permit No. ACT 1007/005
Ownership Category ☐ State ☒ Federal ☐ Fee ☐ Mixed
Date of inspection 8/18 - 8/21, 19 92
Time of inspection 8/18 2:00 ☐ a.m. ☒ p.m. to 8/21 3:00 ☐ a.m. ☒ p.m.
Operator Name (other than Permittee) _____
Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is ☐ is not ☐ expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED RETURN RECEIPT:

P 074 978 439

Date of service/mailling 8/26/92 Time of service/mailling 3:15 ☐ a.m. ☒ p.m.

Permittee/Operator representative

Title

Signature

PRISCILLA BURTON

Division of Oil, Gas & Mining representative

Priscilla Burton

Signature

Title

INSPECTOR

Identification Number

#37

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 92-37-4-1

Violation No. 1 of 1

Nature of violation

Failure to implement sediment control measures as described in the construction plan and consequently conducting coal mining operations outside of the permit area. (D + B)

Provisions of act, regulations or permit violated

R 645-301-752
R 645-300-140 through 143.

Portion of operation to which notice applies

Overland conveyor construction from the eastern end of the conveyor bench to the Rail Road load out.

Remedial action required (including any interim steps)

1. Clear the highway culverts of obstructions
2. discontinue disturbance outside of the permit area
3. reclaim all areas outside of the permit and control sediment within the permit area.
4. maintain sediment control off the permit area until off-permit areas have established vegetation which will control erosion.

Step 1 abatement date is 5pm Sept 4, 1992 (Friday).

Step 2 abatement date is immediate upon receipt.

Step 3 abatement date is Sept. 18, 1992 at 5pm (Friday).

Step 4 abatement is on going until vegetation is established can be abated Sept 18, 1992 5pm Friday or when sediment control is in place.